Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO1300Work Order Type: WeatherizationAudit Name: 14014SO1300

CLIENT INFORMATION

Client Name: 14014SO1300 Address: , Unit 1247

Client ID: 14014SO1300 Culleoka, TN 38451

Alt. Client ID: Maury

CLIENT CONTACT INFORMATION

14014SO1300 Applicant/Person of ✓

Record

<u>AGENCY INFORMATION</u>

Agency: South Central Human Resource Agency Agency Phone: (931) 433-7182

Address: 1437 Winchester Highway Fax: (931) 438-0074

Fayetteville, TN 37334 *Email Address:*

Agency Contact: Ford, Duane Work Phone:

Cell Phone: (615) 308-7878

Email Address: Fordd@hughes.net

Company Name & License Number: _	
Contractor's Signature:	

COMMENT

Client Name: 14014SO1300 Client ID: 14014SO1300 Alt. Client ID: Maury Work Order (Bid Form)
Work Order Name: 14014SO1300
Report Run On: 5/14/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 7

-	Measure 1 Infilt	ration Redctn			Componen	ts			Inspec	ted
C	2. Instal 3. Repa 4. Re-gl 5. Repa 6. Masti 7. Air se 8. Bedro 9. Clear 10. Cau 11. Clea 12. Air se 13. Clea 14 Air se 15. Air se	ir/Replace broken windown I foundation vent covers. Ir leak in and around bathwaze wood windows and coir leak in front of home. It is return air plenum. It is all living room closet. It is caulk jambs, casing, and likklitchen and dining room to caulk upstairs steps. It is all windows are caulk upstairs walls, ceits all DWH compartment. It is all bathroom linen closes air ductwork and mastic results walls are ductwork and mastic results.	tub & recall windows illing, corn	ns. seats. g and						
	то. пер	an addition and mastic i	egisters.		Estimated	ı		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Tota	a/
1	Miscellaneous Supplies	Infiltration Reduction	Each	1						
2	Labor	labor	Each							
C	Other Detail									
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									

Client Name: 14014SO1300 Client ID: 14014SO1300 Alt. Client ID: Maury Work Order (Bid Form)
Work Order Name: 14014SO1300
Report Run On: 5/14/2010

DOE Weatherization Assistant Version 8.5.0

Page 2 of 7

	Measure 2 DW	H Pipe Insulation			Componen	ıts			Inspected	
C	comment									
					Estimated	1		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	DHW Pipe Insulation	Each	1						
		All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.								
2	Labor	DHW Pipe Insulation	Each	1						
C	Other Detail									
				Measur	e Sub Total:		,	Sub Total:		
	Measure 3 Floo	or Ins. R-19			Componen	nts Crawl			Inspected	
					Estimated	1		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1440						
2	Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	1440						
(Other Detail	1								
L										
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									

Client Name: 14014SO1300 Client ID: 14014SO1300 Alt. Client ID: Maury

Report Run On: 5/14/2010

DOE Weatherization Assistant Version 8.5.0 Page 3 of 7

	re 4 Rep lock	olace 2 Back door units,	WS, DS,		Componen	ts		ı	nspected
Comme	nt								
					Estimated	<u> </u>		Actual	
# Materia	al / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors		Replace 2 Back door units	Each	1					
2 Labor		labor	Each						
Other De	tail								
				Measur	e Sub Total:			Sub Total:	
Measui Commei	Air	AC Contractor to Evaluat Plenum Upstairs	e a Retui	rn					nenactor
		rienum opstans			Componen Estimated			Actual	Inspected
# Materia	al / Labor	Description / Comment	Units				Qty		Total
	g	·	<i>Units</i> Each	Qty 1	Estimated	·	Qty	Actual	
1 Heating	g	Description / Comment		Qty	Estimated	·	Qty	Actual	
1 Heating Equipn	g nent	Description / Comment HVAC Return and piping	Each	Qty	Estimated	·	Qty	Actual	
1 Heating Equipn 2 Labor	g nent	Description / Comment HVAC Return and piping	Each	Qty	Estimated	·	Qty	Actual	
1 Heating Equipn 2 Labor	g nent	Description / Comment HVAC Return and piping	Each	Qty	Estimated	·	Qty	Actual	
1 Heating Equipn 2 Labor	g nent	Description / Comment HVAC Return and piping	Each	Qty 1	Estimated	·		Actual	
1 Heating Equipn 2 Labor	g nent <i>tail</i>	Description / Comment HVAC Return and piping	Each	Qty 1	Estimated Unit Cost	·		Actual Unit Cost	

-	Measure 6 Dig	ital Thermostat			Componer	nts			Inspected
C	omment								
					Estimated	d		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipment	DigitalThermostat	Each	1					
		Includes labor cost. Must be equal to Honeywell's PRO 4000 Programmable Thermostat. Must be installed by a qualified technician. Must train homeowner on operation of thermostat. Refer to Appendix A- Standards for Weatherization Materials and South East Field Guide Manual							
2	Labor	labor	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Measure 7 Pres	sureRelief Piping Need	ded		Compone	nts			Inspected
				Estimate	d		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Pressure relief piping	Each	1					
2 Labor	Labor	Hour	1					
Other Detail						,		
			Measur	e Sub Total:			Sub Total:	
	ace/ Fix Not Operation aust Fan	ui itilonei	•	Compone: Estimate			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items		Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								

Measure 9 Sm	oke/ CO2 Detector Com	bo		Componen	ts			nspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	y Smoke/CO2 Detector Combo	Each	1					
2 Labor	Labor	Hour	1					
Other Detail	1		1			1		
				- Out Total]	Sub Total:	
			weasur	e Sub Total:			Sub Total.	
	oor Barrier Needed sement/Crawlspace)			Componen	ts		ı	Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	y Basement / crawlspace vapor barrier	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work O	rder Gra	nd Total:		Gran	d Total:	